


Scale Wiring with six pair cable



Connect each component cable into 1 input connector.

Connect the single output cable to the end connector on the control box.

